# BGE 2022 Submission of Supplemental Projects for Inclusion in the Local Plan





**Process Stage:** Submission of Supplemental Project for inclusion

in the 2022 Local Plan 09/23/2022

## **Previously Presented:**


Need 07/12/2021 Solution 08/13/2021

## **Specific Assumption Reference:**

- Transmission infrastructure replacements (EOL/condition/obsolescence) that are consistent with efficient asset management decisions
- Programmatic review and/or replacement of breakers, relays, wood poles, cables, etc.

# **Problem Statement:**

 Pumphrey 115kV circuit breakers #B22, B28 and B29 installed in 1975 are in deteriorating condition due to compressor issues, leaks, replacement part availability and elevated maintenance costs







**Process Stage:** Submission of Supplemental Project for inclusion

in the 2022 Local Plan


**Selected Solution:** 

Replace Pumphrey circuit breakers #B22, B28, B29

**Estimated Cost**: \$5.2M

**Projected In-Service:** 11/30/2021

**Supplemental Project ID**: S2589







Process Stage: Submission of Supplemental Project for inclusion

in the 2022 Local Plan 09/23/2022

# **Previously Presented:**


Need 07/12/2021 Solution 08/13/2021


# **Specific Assumption Reference:**

- Transmission infrastructure replacements (EOL/condition/obsolescence) that are consistent with efficient asset management decisions
- Programmatic review and/or replacement of breakers, relays, wood poles, cables, etc.

#### **Problem Statement:**

 Windy Edge 115kV circuit breaker #B27 installed in 1971 is in deteriorating condition due to compressor issues, leaks, replacement part availability and elevated maintenance costs







**Process Stage:** Submission of Supplemental Project for inclusion

in the 2022 Local Plan 09/23/2022


**Selected Solution:** 


Replace Windy Edge circuit breaker #B27

**Estimated Cost**: \$1M

**Projected In-Service:** 11/30/2021

**Supplemental Project ID**: S2590







**Process Stage:** Submission of Supplemental Project for inclusion

in the Local Plan 9/26/2022

# **Previously Presented:**

Need 2/17/2022 Solution 3/17/2022

Project Driver: Equipment Material Condition, Performance, and


Risk


# **Specific Assumption Reference:**

- Transmission infrastructure replacements (EOL/condition/obsolescence) that are consistent with efficient asset management decisions
- Programmatic review and/or replacement of breakers, relays, wood poles, cables, etc.

#### **Problem Statement:**

 Windy Edge 115kV circuit breaker #B6 installed in 1971 is in deteriorating condition due to oil leaks, air system leaks, operational problems that led to several failures-to-close and elevated maintenance costs







**Process Stage:** Submission of Supplemental Project for inclusion

in the Local Plan 9/26/2022


**Selected Solution:** 


Replace Windy Edge 115kV circuit breaker #B6

Estimated Cost: \$1.3M

**Projected In-Service:** 4/7/2022

**Supplemental Project ID**: S2722







**Process Stage:** Submission of Supplemental Project for inclusion

in the Local Plan 9/26/2022

# **Previously Presented:**

Need 2/17/2022 Solution 3/17/2022

Project Driver: Equipment Material Condition, Performance, and


Risk


# **Specific Assumption Reference:**

- Transmission infrastructure replacements (EOL/condition/obsolescence) that are consistent with efficient asset management decisions
- Programmatic review and/or replacement of breakers, relays, wood poles, cables, etc.

#### **Problem Statement:**

 Windy Edge 115kV circuit breaker #B32 installed in 1991 is in deteriorating condition due to oil leaks, hydraulic issues, replacement part availability and elevated maintenance costs







**Process Stage:** Submission of Supplemental Project for inclusion

in the Local Plan 9/26/2022


**Selected Solution:** 

Replace Windy Edge 115kV circuit breaker #B32

Estimated Cost: \$1.3M

**Projected In-Service:** 5/6/2022

**Supplemental Project ID**: S2723







**Process Stage:** Submission of Supplemental Project for inclusion

in the Local Plan 9/26/2022

# **Previously Presented:**

Need 2/17/2022 Solution 3/17/2022

Project Driver: Equipment Material Condition, Performance, and


Risk


# **Specific Assumption Reference:**

- Transmission infrastructure replacements (EOL/condition/obsolescence) that are consistent with efficient asset management decisions
- Programmatic review and/or replacement of breakers, relays, wood poles, cables, etc.

#### **Problem Statement:**

 Windy Edge 115kV circuit breaker #B26 installed in 1967 is in deteriorating condition due to heater issues, low pressure issues, replacement part availability and elevated maintenance costs







**Process Stage:** Submission of Supplemental Project for inclusion

in the Local Plan 9/26/2022


**Selected Solution:** 

Replace Windy Edge circuit breaker #B26

Estimated Cost: \$1.3M

**Projected In-Service:** 6/3/2022

**Supplemental Project ID**: S2724



# **Revision History**

9/23/2022 – V1 – Posted Local plan for S2589 and S2590

9/27/2022 - V2 - Posted Local plan for s2722-s2724

BGE Local Plan - 2022