



# Executive Summary Manual Changes

<b>Effective Date</b>	11/19/2024
<b>Impacted Manual #(s)/Manual Title(s):</b> Manual 15: Cost Development Guidelines	
<b>Conforming Order(s):</b>	
<b>Associated Issue Tracking Title:</b>	
<b>Committee Approval Path - What committee(s) have already seen these changes?</b> CDS, MIC/MRC, MC	
<b>MRC 1<sup>st</sup> read date:</b>	8/21/2024
<b>MRC voting date:</b>	9/25/2024
<b>Impacted Manual sections:</b> 2.4, 2.6.11, 4.4, 5.4, 6.4, 7.2, 11.2.1, 13.3, Attachment B	
<b>Reason for change:</b> Biennial review changes	
<b>Summary of the changes:</b> Throughout – standardize spelling of no-load 2.6.11 - Remove table of original VOM Default values to avoid confusion 2.4, 4.4, 5.4, 6.4 - Remove errant "+" from the Startup Cost formula and change TRFC to TFRC 6.4 - Remove blank Note: box 7.2 - Remove (()), fix errant ")", fix summation notation 11.2.1 - Correct the fuel cost formula by changing the multiplication to division 13.3- Remove "Name to be determined" from Exhibit 26 Att. B - Update graphs to have appropriate Y-axis labels Update numbering of sections 3.3.1, 3.3.2, 4.3.1, 6.3.1, 6.3.2, 7.3.1	